

AP checklist - abbreviated

=== Pre-sortie steps

- Insert charged battery; verify charge
- ISO [1000]
- Shooting mode [S]
- Shutter speed [1000]
- Camera clock time zone [UTC]
- Camera clock sync [GPS time]
- Format storage card
- Carefully* clean lens if needed

=== Post-sortie steps

- Remove equipment from aircraft
- Place battery on charger
- Copy images to PC
- Geotag images; deliver to customer
- Clean equipment; return to secure storage

=== END OF CHECKLIST ===